


← TURN ← LEFT-HAND THREAD ←

# BERNZOMATIC®

Distributed by **BROMIC**

Use only with torches designed for Oxygen gas. Read and follow important safety warnings on side label.



## **⚠ DANGER**

**EXTREMELY FLAMMABLE  
FIRE/EXPLOSION HAZARD  
CONTENTS UNDER PRESSURE  
OXIDIZER**

**NET WEIGHT 1.4 oz. / 40.1 g**

**O  
OXYGEN**



**DANGER:** May cause or intensify fire; oxidizer. Keep away from clothing and other combustible materials. Keep valves and fittings free from oil and grease. In case of fire: Stop leak if safe to do so. Store in a well-ventilated place. **Intentional misuse by deliberate concentrated inhalation may cause injury or death.**



**WARNING:** Contains gas under pressure; may explode if heated. Protect from sunlight. Failure to comply with these warnings and instructions may result in an explosion or fire that may cause property damage, personal injury or death.

**BEFORE USE** 1. Read and follow all instructions in torch owner's manual and on propane, MAPP® or MAP-Pro™ gas cylinder. 2. Check cylinder and torch seals. Never use with damaged or missing seals. Discard cylinder if dirt or rust particles are in valve area. 3. Turn off torch. 4. Attach cylinder outdoors away from pilot lights, flames, sparks, and other ignition sources. 5. Attach cylinder away from highly combustible materials, especially grease or oil. Never put oil or grease on any part of cylinder or torch. Escaping gas can ignite these materials without flame or spark 6. Screw counterclockwise to attach cylinder to oxygen regulator connection of Oxygen/Propane, Oxygen/MAPP® or Oxygen/MAP-Pro™ torch. Cylinder has left hand threads. 7. Hand tighten only. Over-tightening will damage seals or threads. 8. Check for leaks by putting soapy water on connections and looking for bubbles. **DURING USE** 1. Never use with standard propane, MAPP® or MAP-Pro™ gas torches. Use only with torches designated for oxygen gas. 2. Use only in well ventilated areas. 3. Never use near pilot lights, flames, sparks, and other ignition sources. 4. Never use near highly combustible materials, such as oil and gas. 5. Do not inhale cylinder contents. Gas in cylinder is not approved for internal or medical use.

**DOT-39 NRC 494/618 M1003**

**AFTER USE** 1. Turn off torch. Let cool. 2. Detach torch when not in use. 3. Detach and store away from pilot lights, flames, and sparks. Escaping gas can enlarge existing fires. 4. Store away from highly combustible materials, especially grease or oil. Escaping gas can ignite these materials without flame or spark. 5. Replace cap to keep valve clean.

**HANDLING & STORAGE** 1. Keep out of reach of children. 2. Keep away from heat, sparks, or flame. Never store at temperatures above 120°F (49°C). 3. Never store in living spaces. 4. Never refill this cylinder. Refilling may cause explosion. Federal law forbids transportation if refilled – penalty up to \$500,000 fine and 5 years imprisonment (49 U.S.C. 5124). 5. Never put in luggage or take on trains or aircraft. 6. To discard, contact local refuse hauler or recycle center. Never put in fire or incinerator. Do not puncture.

**⚠ Intentional misuse by deliberate concentrated inhalation may cause injury or death.**

MAP-Pro™ is a trademark of Worthington Industries. MAPP® is a registered trademark of the BOC Group, Inc.



Visit [bernzomatic.com/cylindersafe](http://bernzomatic.com/cylindersafe) for disposal information.

**BROMIC**  
PLUMBING

10 Phiney Place  
Ingleburn, Sydney, NSW 2565  
**T** 1300 276 642  
**NZ** 0508 276 642  
**E** [plumbing@bromic.com](mailto:plumbing@bromic.com)  
**W** [bromicplumbing.com](http://bromicplumbing.com)

Made in the USA with global components.  
Do not remove or deface this label.

**Part No. 1811420  
Bromic Plumbing**

Emergency Contact: CHEMTREC at  
1-800-424-9300 or International  
1-703-527-3887

**VISIT BERNZOMATIC.COM  
FOR PRODUCT SUPPORT**



436632 0322